Work Orde August 4, 2010	er ID 61024 9:56:29 AM				1		3				Page
Revision ID:	D412-726-142 Wearplate RH		Accept					_	Start		
Start Date: Required Date: Reference:	8/04/10 Start Qty: 1.0 8/11/10 Req'd Qty: 1.0	1 100101 1101 1201		Cust Item I Customer:	D :						
Approvals:	Process Plan: QC:	Date: <u>164-04</u>	Tooling: SPC (Y/N):		ate: ate:				Start Stop		
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr				1						- Camp
N/A	Rev N/A								1		
DC Document Control	DOCUMENT CON' Memo Photoco	ΓROL py bluefile and create labels per	0.00 0.00 PPP D412-726-142 CH	1G001 S (38	loy		!	N	1 (0-8-6	Y
110 Packaging Packaging	Pick Kit Memo		0.00		: ! ! ! ! !			[c	4/	1/4	<u>(</u>
120 QC Quality Control	QC4-100% Inspect Memo	kits for completeness	0.00 S (a)	roloy							,

Dart Ae	rospace	Ltd								· ·
W/O:			WC	ORK ORDER CH	ANGES					<u> </u>
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
							:			
Part No):	PAR #:	Fault Cate	gory:	NC	R: Yes	Vo D)A:	Date: _	
	Res	solution:	Dispositio	n:	QA	: N/C Clo	sed: _		Date: _	*
NCR:			WORK ORD	ER NON-CONFO	RMANCI	E (NCR)			
DATE	STEP	Description of NC		Corrective Action	Section B		Veri	ication	Approval	Approva
DATE	SIEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	otion 	Sign & Date	Se	tion C	Chief Eng	QC Inspect

										+

Work Order ID 61024

August 4, 2010 9:56:29 AM

Required Date: 8/11/10



Page 2

Item ID:

D412-726-142

Accept

Setup Start



Revision ID:

Item Name:

Wearplate RH

Start Date:

8/04/10

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Run Start

Stop

Stop



Approvals:

Reference:

Process Plan: _____ Date: ____ Tooling:

QC: _____ Date: ____ SPC (Y/N):

Set Up/

Run Hours

Tool ID

Date:

Date:

Tool # Plan

Code

Accept

Reject

Insp.

Work Center ID

130

Sequence ID/

Packaging Packaging

Memo

Operation

Description

Packaging

0.00

0.00

Identify and pack for shipping as per PPP D412-726 142 Decation: PPP Rev:

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Reject **Q**ty Qty |

Number

Stamp

Dart Aeros	pace Ltd
------------	----------

									-
W/O:			WO	RK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No D e)A:	_ Date: _	
	Re	esolution:	Disposition	:	QA: N/C Cld	sed: _		Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCR)			
		Description of NC		Corrective Action Section		Veri	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ction C	Chief Eng	QC Inspector
	1	I .			ŀ		1	\$	1

Work Order ID: 61024 - Tach Tale John Land Tale Start Date: 80412-726-142 Amounted Date: Start Date: 80410	Picklist Print August 4, 2010 9:56:33 AM												Page 1
Component Item ID	Parent Item: D412-726-142			0 8181 11811 11818 11818 1 18 1811 81881 11818 1181 117	10 10 10 10 10 10 10 10			į					4
	Comments: IPP Rev:A□0	5.05.12□New issue□I	KJ/JLM	[
Bolt Location ST350 1122 105057 10502 Location ST348 2739 110985 2739 1109									Qty per Kit		Qty Issued		Status
Location Loc Otv Coc Code		Purchased	No			120	Each	t .		40 —		4	<i></i>
Location Loc Otv Loc Code	N960JD10L NAS1149D03	^{32J} Purchased	No	ST350		1	122 622 500	i 	40 · r	40		L	/
D3315-2 Manufactured No	Vasiici			ST348	110985	2	739	Loc Code	_			:	
Location Loc Qtv Loc Code ST496 3 ST496 3 ST2228 3 ST2238 3 ST496		Manufactured	No					3.0000		11 ~	· 	R	
Location Loc Oty Loc Code ST496 6		Manufactured	No	ST496	52228		3	6.0000	1 t	32)-24			17
į l	Warplate .			ST496	52229	<u>Loc Q</u>	6	1	:	53229		1	!4¥4 (

Part No):	PAR #:	Fault Category:	NCR : Ye	s No Do	PA:	Date: _	
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
V/O:			WORK ORDER	CHANGES				

NCR:		·	WORK ORDE	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verilication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Seption C	Chief Eng	QC inspector

· ·			! !	
Picklist Print August 4, 2010 9:56:33 AM				Page 2
Work Order ID: 61024 Parent Item: D412-726-142 Parent Item Name: Wearplate RH			Start Date: 8/04/10 Start Qty: 1/00	Required Date: 8/11/10 Required Qty: 1.00
D3315-6 Manufacture	d No	120 Each	4.0000 1 1	(10/8/4 (
	<u>Location</u> ST496A 36173	<u>Loc Oty</u> 4 4	Loc Code	773
			; ,	

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			WORK ORDER C	HANGES				
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						· ·		
								<u> </u>
					,		·	
Part No		PAR #:	Fault Category:	NCR: Yes	No D	١.	Deter	

	Re	esolution:	Disposition	n:	QA: N/C Clos	sed:	Date:		
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)				
		Description of NC		Corrective Action Section	on B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	
	,							:	
		·							
		ł							

4.0 **WEIGHT AND BALANCE**



There is negligible weight change associated with the installation of the Dart wearplates.

5.0 **PARTS LIST**

Qty -111	Qty -141	Qty -142	Qty -211	Qty -241	Part Number	Description
Х					D412-726-111	WEARPLATE KIT (205/212/412
				•		Standard Skidtubes)
	Х	•			D412-726-141	WEARPLATE KIT (205/212/412
						Standard Skidtubes), LH
		X			D412-726-142	WEARPLATE KIT (205/212/412
						Standard Skidtubes), RH
			Х		D412-726-211	WEARPLATE KIT (412 Float
						Skidtubes)
ł		j		Х	D412-726-241	WEARPLATE KIT (412 Float
						Skidtubes), LH/RH
1	1				D3315-1	WEARPLATE (LH FWD)
1		1			D3315-2 /	WEARPLATE (RH FWD)
1	1				D3315-3	WEARPLATE (LH CENTER)
1		1			D3315-4	WEARPLATE (RH CENTER)
11	1				D3315-5	WEARPLATE (LH AFT)
1		1			D3315-6	WEARPLATE (RH AFT)
			2	1	D3321-1	WEARPLATE (LH FWD, RH MIDDLE)
			2	_ 1	D3321-2	WEARPLATE (RH FWD, LH MIDDLE)
			2	11	D3321-3	WEARPLATE (AFT END)
80	40	40	80	40	AN3-5A	BOLT
80	40	40	80	40	AN960JD10L	WASHER